



# **FOCUS TECH** *Process Chemicals*

## **Technical Data Sheet**

### **Focus Tech FS-72/OL**

#### **Photoresist Stripper**

#### ***Product Description***

---

FS-72/OL is a photoresist stripper concentrate formulated specifically for use with today's multipurpose and plating photoresists. FS-72/OL is formulated to break the resist into very small piece sizes to aid in removal from fine and/or overplated features without the use of glycol ethers. FS-72/OL strips quickly at very low concentrations and leaves the copper surface clean and free of oxidation. FS-72/OL is designed to completely remove the tenacious adhesion promoters used in many of today's photoresists.

#### ***Physical Properties***

---

Specific gravity: 1.0  
pH: > 13  
Appearance: clear, light amber liquid  
Flash point: > 200 °F

#### ***Typical Operating Parameters***

---

Concentration: 6 - 10% v/v  
Temperature: 120 – 140 °F

#### ***Storage***

---

Store in original containers above 40 °F.

#### ***Safety***

---

CAUTION! FS-72/OL concentrates and working solutions contain strong alkaline ingredients. Avoid contact with eyes, skin and clothing. Wear chemical handler's gloves, goggles and protective clothing when handling. Read and understand Material Safety Data Sheet before using this product.

#### ***Notice***

---

The information and recommendations, contained herein, regarding this product are, to the best of our knowledge, true and accurate. We make no guarantee of results because the conditions of actual use are beyond our control. We assume no liability for damages or penalties resulting from the use of this product or following our recommendations. Our recommendations and suggestions for use of this product are not intended to grant license to operate under or infringe any patent.